

ASSMANN WSW components, Inc. 1840 W. Drake Drive, Suite 101 Tempe, AZ 85283 Toll Free 877.277.6266 www.assmann.us

## **Product Change Notification (PCN)**

Issue Date: 5/15/2014 Modification/Revision Date: 5/15/2014

**D-Sub** 

Change Notification: PCN-US-20140522-DSUB

Description of changes: Change of Production Location

**Change of Part Numbers** 

"-R" is removed from old part number

**INVENTORY ACTION** 

Inventories at ASSMANN WSW will be shipped per our standard

shipping algorithm. Customers may receive either part

number through transition until the old part number is consumed.

Date of change and Implementation: Change: 5/15/2014

Key Characteristics of Change: Change of part number

Products Affected:

A-DSF25LPXX-III-R ADS25A-KG-TASB5-R

Reason for Change: Part number unification

Response: No response to this notification is required.



ASSMANN WSW components, Inc. 1840 W. Drake Drive, Suite 101 Tempe, AZ 85283 Toll Free 877.277.6266 www.assmann.us

## **Product Change Notification (PCN)**

Issue Date: 5/15/2014
Modification/Revision Date: 5/15/2014

## **Reference Documents / Attachments:**

**Document: Drawing** 

Previous part number	New part number	Drawing number
A-DSF25LPXX-III-R	A-DSF-25LPIII/Z	ASS_4891_COrev06
ADS25A-KG-TASB5-R	ADS25A-KG-TASB5	ASS_6115_COrev00