



Product Change Notification

Current Date: 21-Jun-2023

TE Connectivity

Product Change Notification: P-23-024747

PCN Date: 20-JUN-23

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Multiple part numbers

Description of Changes
Change the shipping point from EP20 and WCDC to HL20, HL30 or HL40

Reason for Changes:	
Product improvement.Optimize the shipping routes, using national shipping points for local customers.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	07-JUL-2023
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-316837-2	NO						
1-936119-2	NO						
1123343-1	NO		TYC1123343-1	"EM3607-000", "AMP-0-1123343-1"			
1318382-8	NO		TYC1318382-8				
1318384-2	NO		TYC1318384-2				
1318386-1	NO		TYC1318386-1				
1318917-1	NO		TYC1318917-1				
1376109-1	NO		TYC1376109-1				
1473252-1	NO		TYC1473252-1				
1473284-1	NO		TYC1473284-1				
1473672-1	NO		TYC1473672-1	"EM3606-000", "AMP-0-1473672-1"			
1674298-1	NO		TYC1674298-1				
1674311-1	NO		TYC1674311-1				
1674742-1	NO		TYC1674742-1				
171630-1	NO		TYC171630-1	"0-0171630-1"			
171630-5	NO						
171661-1	NO		TYC171661-1				
171661-2	NO		TYC171661-2				
1717118-1	NO		TYC1717118-1				
173630-1	NO		TYC173630-1	"0-0173630-1"			
173631-1	NO		TYC173631-1				
173631-6	NO		TYC173631-6	"TL004"			
173633-1	NO		TYC173633-1	"0-0173633-1"			
173645-1	NO		TYC173645-1				
173645-2	NO			"0-0173645-2"			
173716-1	NO		TYC173716-1				
173852-1	NO		TYC173852-1				
173853-1	NO		TYC173853-1				
174045-2	NO		TYC174045-2				
1743059-2	NO		TYC1743059-2				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
174352-2	NO		TYC174352-2	"440-483671", "CA9317-000", "AMPS-0-0174352-2"			
1746872-1	NO						
174923-1	NO		TYC174923-1	"0-0174923-1"			
174930-1	NO		TYC174930-1				
175265-1	NO		TYC175265-1				
175966-2	NO		TYC175966-2				
175967-2	NO		TYC175967-2				
176116-6	NO		TYC176116-6				
179631-1	NO		TYC179631-1				
1827855-1	NO						
1897462-2	NO						
1939351-1	NO		TYC1939351-1				
1981562-1	NO						
2303790-1	NO						
2822357-1	NO		TYC2822357-1				
316837-2	NO		TYC316837-2				
936054-1	NO		TYC936054-1				
936121-1	NO		TYC936121-1				



Product Change Notification

Current Date: 21-Jun-2023

TE Connectivity

Product Change Notification: P-23-024747

PCN Date: 20-JUN-23

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Multiple part numbers

Description of Changes
Change the shipping point from EP20 and WCDC to HL20, HL30 or HL40

Reason for Changes:
Product improvement.Optimize the shipping routes, using national shipping points for local customers.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	07-JUL-2023
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-936119-2	NO						
1123343-1	NO		TYC1123343-1	"EM3607-000", "AMP-0-1123343-1"			
1318386-1	NO		TYC1318386-1				
1473252-1	NO		TYC1473252-1				
1473284-1	NO		TYC1473284-1				
1473672-1	NO		TYC1473672-1	"EM3606-000", "AMP-0-1473672-1"			
171661-1	NO		TYC171661-1				
171661-2	NO		TYC171661-2				
173630-1	NO		TYC173630-1	"0-0173630-1"			
173631-1	NO		TYC173631-1				
173633-1	NO		TYC173633-1	"0-0173633-1"			
173645-1	NO		TYC173645-1				
173645-2	NO			"0-0173645-2"			
173852-1	NO		TYC173852-1				
173853-1	NO		TYC173853-1				
174045-2	NO		TYC174045-2				
1743059-2	NO		TYC1743059-2				
174352-2	NO		TYC174352-2	"440-483671", "CA9317-000", "AMPS-0-0174352-2"			
1746872-1	NO						
174923-1	NO		TYC174923-1	"0-0174923-1"			
174930-1	NO		TYC174930-1				
175265-1	NO		TYC175265-1				
175966-2	NO		TYC175966-2				
175967-2	NO		TYC175967-2				
179631-1	NO		TYC179631-1				
1827855-1	NO						
1897462-2	NO						
1939351-1	NO		TYC1939351-1				
1981562-1	NO						
2303790-1	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2822357-1	NO		TYC2822357-1				
936054-1	NO		TYC936054-1				
936121-1	NO		TYC936121-1				