



Product Change Notification

Current Date: 07-Jul-2023

TE Connectivity

Product Change Notification: PCN-23-169918

PCN Date: 03-JUL-23

Customer: Heilind Electronics
Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Part and Drawing revision level match

Description of Changes

Dear valued customer, In an effort to maintain same revision level of parts across entire documentation and to avoid conflicts between revision in shipping labels to drawings, we are aligning Product drawing revision & Central Part Registry revision level. Also we use this opportunity to fix rounding and conversion errors (from inch to mm / mm to inch) to avoid mismatch between Product drawing and shipping labels. This change is for administrative purpose only and there is no change in Form, Fit and Functions of the product. This change will be processed with PPAP level 1 / First Article Inspection (FAI). If you need PPAP document, then apply for e-PPAP. Existing inventory to be consumed in First In First Out (FIFO) basis. (There is a cooling period of 180 days upto which part with old labels can be shipped) We thank you for your business and look forward to servicing you through our standard part offerings in the future.

Reason for Changes:

Update made to improve document clarity

PCN Attributes:

| | |
|--------------------------|-----------------------------------|
| Product Category: | Kind of Change: |
| Heat Shrink Tubing | Drawing |
| Change Feature: | Potential Customer Impact: |
| Revision Adjustment | No Customer Impact |
| Remarks: | |

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Ship Date of Changed Items (Changed Parts Only): |
| | 31-MAR-2023 |
| Last Ship Date of Changed Items (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |
| Effectivity Date: | Date of First Samples: |
| | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| EL88812001 | NO | | | "PROV-VERSAFIT-3/4-0-STK", "1899841-3" | | | |
| EL93562001 | NO | | | "PROV-VERSAFIT-3/4-9-STK", "3-1899841-3" | | | |
| EM69614001 | NO | | | "VERSAFIT-3/16-7-SP", "7-1899845-7" | | | |
| EM82616001 | NO | | | "VERSAFIT-3/4-2-64MM" | | | |
| EP42216001 | NO | | | "VERSAFIT-1/4-6-30MM" | | | |
| NB14124001 | NO | | | | | | |
| NB14134001 | NO | | | "VERSAFIT-1/2-0-SP" | | | |
| NB14154001 | NO | | | | | | |
| NB14164001 | NO | | | | | | |
| NB14184001 | NO | | | | | | |
| NB14254001 | NO | | | | | | |
| NB14284001 | NO | | | "VERSAFIT-1-0-SP." | | | |
| NB14314001 | NO | | | | | | |
| NB14354001 | NO | | | "VERSAFIT-3/4-0-FSP" | | | |
| NB14374001 | NO | | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14434001 | NO | | | | | | |
| NB14474001 | NO | | | | | | |
| NB14494001 | NO | | | | | | |
| NB14524001 | NO | | | | | | |
| NB14594001 | NO | | | | | | |
| NB14604001 | NO | | | | | | |
| NB14614001 | NO | | | | | | |
| NB14644001 | NO | | | | | | |
| NB14654001 | NO | | | | | | |
| NB14664001 | NO | | | | | | |
| NB14674001 | NO | | | | | | |
| NB14704001 | NO | | | | | | |
| NB14714001 | NO | | | | | | |
| NB14734001 | NO | | | | | | |
| NB15014001 | NO | | | | | | |
| NB16924001 | NO | | | | | | |
| NB16934001 | NO | | | "VERSAFIT-3/64-0-SP" | | | |
| NB16984001 | NO | | | | | | |
| NB17694001 | NO | | | | | | |
| NB17744001 | NO | | | | | | |
| NB17754001 | NO | | | | | | |
| NB19914001 | NO | | | "VERSAFIT-1/16-0-SP" | | | |
| NB19994001 | NO | | | | | | |
| NB20014001 | NO | | | | | | |
| NB20034001 | NO | | | | | | |
| NB20074001 | NO | | | | | | |
| NB20084001 | NO | | | | | | |
| NB20114001 | NO | | | | | | |
| NB20144001 | NO | | | | | | |
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20204001 | NO | | | | | | |
| NB20224001 | NO | | | | | | |
| NB20234001 | NO | | | | | | |
| NB20274001 | NO | | | | | | |
| NB20344001 | NO | | | | | | |
| NB20364001 | NO | | | | | | |
| NB20374001 | NO | | | | | | |
| NB20384001 | NO | | | | | | |
| NB20394001 | NO | | | | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |
| NB20464001 | NO | | | | | | |
| NB20474001 | NO | | | | | | |
| NB20504001 | NO | | | | | | |
| NB23284001 | NO | | | | | | |
| NB23344001 | NO | | | | | | |
| NB23564001 | NO | | | | | | |

Customer: Heilind Electronics Inc (264685)

Location: Hudson

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14664001 | NO | | | | | | |
| NB20034001 | NO | | | | | | |
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14354001 | NO | | | "VERSAFIT-3/4-0-FSP" | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14354001 | NO | | | "VERSAFIT-3/4-0-FSP" | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |

Customer: Heilind Asia Pacific (3133470)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB16984001 | NO | | | | | | |
| NB19994001 | NO | | | | | | |
| NB20034001 | NO | | | | | | |
| NB20144001 | NO | | | | | | |
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20344001 | NO | | | | | | |
| NB20364001 | NO | | | | | | |
| NB20374001 | NO | | | | | | |
| NB20384001 | NO | | | | | | |
| NB20394001 | NO | | | | | | |
| NB20464001 | NO | | | | | | |
| NB20474001 | NO | | | | | | |
| NB23344001 | NO | | | | | | |

Customer: Heilind Electronics Inc (1275266)

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| EL88812001 | NO | | | "PROV-VERSAFIT-3/4-0-STK", "1899841-3" | | | |
| EM69614001 | NO | | | "VERSAFIT-3/16-7-SP", "7-1899845-7" | | | |
| EP42216001 | NO | | | "VERSAFIT-1/4-6-30MM" | | | |
| NB14124001 | NO | | | | | | |
| NB14134001 | NO | | | "VERSAFIT-1/2-0-SP" | | | |
| NB14164001 | NO | | | | | | |
| NB14184001 | NO | | | | | | |
| NB14254001 | NO | | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14284001 | NO | | | "VERSAFIT-1-0-SP" | | | |
| NB14314001 | NO | | | | | | |
| NB14354001 | NO | | | "VERSAFIT-3/4-0-FSP" | | | |
| NB14374001 | NO | | | | | | |
| NB14434001 | NO | | | | | | |
| NB14474001 | NO | | | | | | |
| NB14494001 | NO | | | | | | |
| NB14604001 | NO | | | | | | |
| NB14614001 | NO | | | | | | |
| NB14644001 | NO | | | | | | |
| NB14664001 | NO | | | | | | |
| NB14704001 | NO | | | | | | |
| NB14734001 | NO | | | | | | |
| NB16934001 | NO | | | "VERSAFIT-3/64-0-SP" | | | |
| NB17694001 | NO | | | | | | |
| NB19914001 | NO | | | "VERSAFIT-1/16-0-SP" | | | |
| NB20014001 | NO | | | | | | |
| NB20034001 | NO | | | | | | |
| NB20074001 | NO | | | | | | |
| NB20084001 | NO | | | | | | |
| NB20114001 | NO | | | | | | |
| NB20144001 | NO | | | | | | |
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20204001 | NO | | | | | | |
| NB20224001 | NO | | | | | | |
| NB20234001 | NO | | | | | | |
| NB20274001 | NO | | | | | | |
| NB20344001 | NO | | | | | | |
| NB20394001 | NO | | | | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |
| NB20464001 | NO | | | | | | |
| NB20504001 | NO | | | | | | |
| NB23344001 | NO | | | | | | |
| NB23564001 | NO | | | | | | |

Customer: Heilind Asia Pacific (Hong Kong) (2980376)

Location: Shatin, N.t.

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14134001 | NO | | | "VERSAFIT-1/2-0-SP" | | | |
| NB14594001 | NO | | | | | | |
| NB20034001 | NO | | | | | | |
| NB20114001 | NO | | | | | | |
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20274001 | NO | | RYCNB20274001 | | | | |
| NB20344001 | NO | | | | | | |
| NB20504001 | NO | | | | | | |

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14354001 | NO | | | "VERSAFIT-3/4-0-FSP" | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |

Customer: Heilind Asia Pacific (3229127)

Location: Suzhou

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB19994001 | NO | | | | | | |
| NB20034001 | NO | | | | | | |
| NB20144001 | NO | | | | | | |
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20344001 | NO | | | | | | |
| NB20364001 | NO | | | | | | |
| NB20374001 | NO | | | | | | |
| NB20384001 | NO | | | | | | |
| NB20394001 | NO | | | | | | |
| NB20464001 | NO | | | | | | |
| NB20474001 | NO | | | | | | |
| NB23344001 | NO | | | | | | |

Customer: Heilind Electronics GmbH (113007)

Location: Feldkirchen- Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB20034001 | NO | | | | | | |

Customer: Maverick Electronics (155785)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14494001 | NO | | | | | | |

Customer: Heilind Asia Pacific (3068918)

Location: Kwai Chung

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20274001 | NO | | | | | | |

Customer: Heilind Electronics Inc (167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| EL88812001 | NO | | | "PROV-VERSAFIT-3/4-0-STK", "1899841-3" | | | |
| EL93562001 | NO | | | "PROV-VERSAFIT-3/4-9-STK", "3-1899841-3" | | | |
| EM69614001 | NO | | | "VERSAFIT-3/16-7-SP", "7-1899845-7" | | | |
| EM82616001 | NO | | | "VERSAFIT-3/4-2-64MM" | | | |
| EP42216001 | NO | | | "VERSAFIT-1/4-6-30MM" | | | |
| NB14124001 | NO | | | | | | |
| NB14134001 | NO | | | "VERSAFIT-1/2-0-SP" | | | |
| NB14154001 | NO | | | | | | |
| NB14164001 | NO | | | | | | |
| NB14184001 | NO | | | | | | |
| NB14254001 | NO | | | | | | |
| NB14284001 | NO | | | "VERSAFIT-1-0-SP." | | | |
| NB14314001 | NO | | | | | | |
| NB14354001 | NO | | | "VERSAFIT-3/4-0-FSP" | | | |
| NB14374001 | NO | | | | | | |
| NB14434001 | NO | | | | | | |
| NB14474001 | NO | | | | | | |
| NB14494001 | NO | | | | | | |
| NB14524001 | NO | | | | | | |
| NB14604001 | NO | | | | | | |
| NB14614001 | NO | | | | | | |
| NB14644001 | NO | | | | | | |
| NB14654001 | NO | | | | | | |
| NB14664001 | NO | | | | | | |
| NB14674001 | NO | | | | | | |
| NB14704001 | NO | | | | | | |
| NB14714001 | NO | | | | | | |
| NB14734001 | NO | | | | | | |
| NB15014001 | NO | | | | | | |
| NB16924001 | NO | | | | | | |
| NB16934001 | NO | | | "VERSAFIT-3/64-0-SP" | | | |
| NB17694001 | NO | | | | | | |
| NB17744001 | NO | | | | | | |
| NB17754001 | NO | | | | | | |
| NB19914001 | NO | | | "VERSAFIT-1/16-0-SP" | | | |
| NB19994001 | NO | | | | | | |
| NB20014001 | NO | | | | | | |
| NB20034001 | NO | | | | | | |
| NB20074001 | NO | | | | | | |
| NB20084001 | NO | | | | | | |
| NB20114001 | NO | | | | | | |
| NB20144001 | NO | | | | | | |
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20204001 | NO | | | | | | |
| NB20224001 | NO | | | | | | |
| NB20234001 | NO | | | | | | |
| NB20274001 | NO | | | | | | |
| NB20344001 | NO | | | | | | |
| NB20374001 | NO | | | | | | |
| NB20384001 | NO | | | | | | |
| NB20394001 | NO | | | | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |
| NB20464001 | NO | | | | | | |
| NB20504001 | NO | | | | | | |
| NB23284001 | NO | | | | | | |
| NB23344001 | NO | | | | | | |
| NB23564001 | NO | | | | | | |

Customer: Heilind Asia Pacific (Hong Kong) (2991513)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14134001 | NO | | | "VERSAFIT-1/2-0-SP" | | | |
| NB14594001 | NO | | | | | | |
| NB20034001 | NO | | | | | | |
| NB20114001 | NO | | | | | | |
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20274001 | NO | | RYCNB20274001 | | | | |
| NB20344001 | NO | | | | | | |
| NB20504001 | NO | | | | | | |

Customer: Heilind Electronics GmbH (3050932)

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB20034001 | NO | | | | | | |

Customer: Heilind Asia Pacific (SG) Pte Ltd (2980456)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| NB14354001 | NO | | | "VERSAFIT-3/4-0-FSP" | | | |
| NB20164001 | NO | | | "VERSAFIT-1/8-0-SP" | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |
| NB20424001 | NO | | | "VERSAFIT-3/32-0-SP" | | | |