



## Product Change Notice

November 21, 2022

Ref: 34-22-010

Dear Song Chuan Precision Americas Customer:

Please be advised that Song Chuan will be changing our 896, 897, 898, MV002 -C relays as described below.

Song Chuan requests your approval for the change described in this letter. Please let us know what the next steps should be.

### Title of Change

896/897/898/MV002 -C Product Change Notice

### Part Number(s) Affected:

896-1CH-C1 12VDC
896H-1CH-C 001 12VDC
896H-1CH-C 12VDC
896H-1CH-C 24VDC
896H-1CH-C1 001 12VDC
896H-1CH-C1 001 24VDC
896H-1CH-C1 12VDC
896H-1CH-C1-R1 U45 12VDC
896H-1CH-C1S 001 24VDC
896H-1CH-C1S 12VDC
896H-1CH-C1S-24VDC
896H-1CH-C-R1 U03 12VDC
896H-1CH-C-T 001 12VDC
897-1AH-C1S-R1 U06 12VDC
897-1AH-C-R1 U03 12VDC
897-1AH-C-R1 U06 12VDC
897P-1AH-C-R1 12VDC
898H-1AH-C 001 12VDC
898H-1AH-C-R1 U04 12VDC
898H-1CH-C 12VDC
898H-1CH-C-R1 U03 12VDC

### Description of Change(s)/Modifications(s)

Housing modification with venting rib for curing process. The vent hole on the cover will be sealed

SONG CHUAN PRECISION AMERICAS, INC.

43 S Powerline Road #602 • Pompano Beach, FL 33069 • Phone: (954) 788-5889

[www.songchuanusa.com](http://www.songchuanusa.com)



Purpose

Necessary change for the automation curing process

Effects/Impact of Change

No change to relay fit, function, performance or specification/drawing. Old version and new version are interchangeable. No effect on cost or delivery.

Implementation timing

Production will begin June 2023.

Respectfully,

Inside Sales Manager  
Song Chuan Precision Americas

**Please acknowledge your notification by signing below and emailing back to me.  
Thank you.**

Acknowledged by: \_\_\_\_\_

Print Name; \_\_\_\_\_

Company Name: \_\_\_\_\_

Position/Department: \_\_\_\_\_

Date: \_\_\_\_\_

*Craig Wood*  
*MASTER ELECTRONICS*  
*3/15*