



Product Change Notification

Current Date: 01-Jun-2023

TE Connectivity

Product Change Notification: P-23-024630

PCN Date: 30-MAY-23

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Multiple part numbers

Description of Changes
TE is changing its system as it relates to minimum order quantities for the part numbers listed to address trends that have been recently observed. We have identified situations where quantities can be ordered at quantities below what our standard packaging requirements allow. The situation also results in non-standard handling (break-pack) and creates risks for damage during transit to our customers. Therefore, we are making changes to align minimum order quantities with appropriate standard packaging requirements for these part numbers.

Reason for Changes:
Product improvement. In addition to the above, please note that this change will become effective on the date listed in this notification for listed part numbers and minimum order quantities. TE will not be liable for any orders placed for shipments after this date that do not meet our new minimum order requirements or other related impacts, e.g., scorecard performance associated with over-shipment quantities. If there are any concerns with alignment in your systems to match new minimum order quantity requirements by the effective date listed, please reach out to your TE account manager as quickly as possible, and at a minimum, 10 working days prior to effective change date. Otherwise, TE will proceed with change for shipments on and after effective date listed.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	10-JUL-2023
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393310-9	NO		TYC1-1393310-9	"26-A1348B", "26A1348B"			
1-1437709-6	NO			"106019/106020", "106020", "106097/106098", "106098", "93FG-14474-BCA"			
1-1452424-1	NO		TYC1-1452424-1				
1-1452424-2	NO						
1-1452688-2	NO						
1-1703930-2	NO		TYC1-1703930-2				
1-2291853-1	NO		TYC1-2291853-1				
1-962915-2	NO		TYC1-962915-2	"8202609392"			
1-962918-2	NO						
1-967067-1	NO		TYC1-967067-1				
1241860-2	NO		TYC1241860-2				
1418762-1	NO		TYC1418762-1				
1418893-1	NO		TYC1418893-1				
142183-1	NO		TYC142183-1				
144969-2	NO		TYC144969-2				
1534130-1	NO		TYC1534130-1				
1544228-1	NO		TYC1544228-1	"P79101792761"			
1544333-1	NO		TYC1544333-1	"P790862"			
1670144-3	NO		TYC1670144-3				
1703014-1	NO		TYC1703014-1				
1717118-1	NO		TYC1717118-1				
1718758-1	NO		TYC1718758-1				
1718762-1	NO		TYC1718762-1				
1719840-1	NO		TYC1719840-1				
174922-1	NO		TYC174922-1	"0-0174922-1"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1802105-1	NO						
2-1393310-0	NO		TYC2-1393310-0	"26-A1348C", "26A1348C"			
2-1703930-1	NO		TYC2-1703930-1				
2-1703930-2	NO		TYC2-1703930-2				
2-963964-4	NO		TYC2-963964-4				
2-963964-7	NO		TYC2-963964-7				
2141868-1	NO						
2141970-3	NO						
2298116-1	NO		TYC2298116-1				
2317509-1	NO						
2317511-1	NO						
282377-1	NO		TYC282377-1				
284080-1	NO		TYC284080-1				
344267-1	NO		TYC344267-1				
345206-1	NO		TYC345206-1				
347874-1	NO		TYC347874-1				
5-1418760-3	NO		TYC5-1418760-3				
5-962886-1	NO		TYC5-962886-1				
5-963715-1	NO		TYC5-963715-1				
5-963716-2	NO		TYC5-963716-2				
5-965906-5	NO		TYC5-965906-5				
5-965908-1	NO		TYC5-965908-1				
5-965982-1	NO		TYC5-965982-1				
6-928918-2	NO		TYC6-928918-2				
638078-1	NO		TYC638078-1				
638078-3	NO		TYC638078-3				
776492-2	NO		TYC776492-2				
828904-2	NO		TYC828904-2				
828921-1	NO		TYC828921-1				
926965-1	NO		TYC926965-1				
927766-3	NO		TYC927766-3	"AMP-0-0927766-3", "E17312-000"			
927768-1	NO		TYC927768-1				
927771-9	NO		TYC927771-9				
927774-1	NO		TYC927774-1				
927829-2	NO		TYC927829-2				
927840-5	NO		TYC927840-5				
929939-1	NO		TYC929939-1	"CF0548-000", "AMP-0-0929939-1", "60.349.00"			
929967-1	NO		TYC929967-1	"820A-37375", "5001140"			
929968-1	NO		TYC929968-1				
962191-1	NO		TYC962191-1				
962942-1	NO		TYC962942-1	"0-0962942-1"			
962943-2	NO		TYC962943-2				
963244-1	NO		TYC963244-1				
964282-1	NO		TYC964282-1				
964306-1	NO		TYC964306-1				
964314-1	NO		TYC964314-1				
967067-1	NO		TYC967067-1	"0-0967067-1", "EG9740-000", "AMP-0-0967067-1"			
968037-2	NO		TYC968037-2				
969005-3	NO		TYC969005-3				



Product Change Notification

Current Date: 01-Jun-2023

TE Connectivity

Product Change Notification: P-23-024630

PCN Date: 30-MAY-23

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Multiple part numbers

Description of Changes
TE is changing its system as it relates to minimum order quantities for the part numbers listed to address trends that have been recently observed. We have identified situations where quantities can be ordered at quantities below what our standard packaging requirements allow. The situation also results in non-standard handling (break-pack) and creates risks for damage during transit to our customers. Therefore, we are making changes to align minimum order quantities with appropriate standard packaging requirements for these part numbers.

Reason for Changes:
Product improvement. In addition to the above, please note that this change will become effective on the date listed in this notification for listed part numbers and minimum order quantities. TE will not be liable for any orders placed for shipments after this date that do not meet our new minimum order requirements or other related impacts, e.g., scorecard performance associated with over-shipment quantities. If there are any concerns with alignment in your systems to match new minimum order quantity requirements by the effective date listed, please reach out to your TE account manager as quickly as possible, and at a minimum, 10 working days prior to effective change date. Otherwise, TE will proceed with change for shipments on and after effective date listed.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	10-JUL-2023
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393310-9	NO		TYC1-1393310-9	"26-A1348B", "26A1348B"			
1-1437709-6	NO			"106019/106020", "106020", "106097/106098", "106098", "93FG-14474-BCA"			
1-2291853-1	NO		TYC1-2291853-1				
1-962915-2	NO		TYC1-962915-2	"8202609392"			
1-962918-2	NO						
1-967067-1	NO		TYC1-967067-1				
1418762-1	NO		TYC1418762-1				
142183-1	NO		TYC142183-1				
1534130-1	NO		TYC1534130-1				
1544228-1	NO		TYC1544228-1	"P79101792761"			
1544333-1	NO		TYC1544333-1	"P790862"			
1670144-3	NO		TYC1670144-3				
1703014-1	NO		TYC1703014-1				
1718762-1	NO		TYC1718762-1				
174922-1	NO		TYC174922-1	"0-0174922-1"			
2-1393310-0	NO		TYC2-1393310-0	"26-A1348C", "26A1348C"			
2141970-3	NO						
2298116-1	NO		TYC2298116-1				
344267-1	NO		TYC344267-1				
347874-1	NO		TYC347874-1				
5-1418760-3	NO		TYC5-1418760-3				
5-962886-1	NO		TYC5-962886-1				
5-963715-1	NO		TYC5-963715-1				
5-963716-2	NO		TYC5-963716-2				
5-965906-5	NO		TYC5-965906-5				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-965908-1	NO		TYC5-965908-1				
5-965982-1	NO		TYC5-965982-1				
6-928918-2	NO		TYC6-928918-2				
638078-1	NO		TYC638078-1				
638078-3	NO		TYC638078-3				
776492-2	NO		TYC776492-2				
828904-2	NO		TYC828904-2				
828921-1	NO		TYC828921-1				
926965-1	NO		TYC926965-1				
927766-3	NO		TYC927766-3	"AMP-0-0927766-3", "E17312-000"			
927768-1	NO		TYC927768-1				
927774-1	NO		TYC927774-1				
927829-2	NO		TYC927829-2				
927840-5	NO		TYC927840-5				
929939-1	NO		TYC929939-1	"CF0548-000", "AMP-0-0929939-1", "60.349.00"			
929967-1	NO		TYC929967-1	"820A-37375", "5001140"			
929968-1	NO		TYC929968-1				
962191-1	NO		TYC962191-1				
962943-2	NO		TYC962943-2				
963244-1	NO		TYC963244-1				
964282-1	NO		TYC964282-1				
964306-1	NO		TYC964306-1				
964314-1	NO		TYC964314-1				
967067-1	NO		TYC967067-1	"0-0967067-1", "EG9740-000", "AMP-0-0967067-1"			
969005-3	NO		TYC969005-3				