






## PRODUCT CHANGE NOTIFICATION – A01 E-stops

### 1/ A01ES operators and switch block new part numbers

Following our PCN ref. 2023012302 and the evolution of the ISO 13850 (2015), the A01ES series E-stops can now only be sold with the validated switch block. Switch block and operators must be ordered together as a new single part number. This modification applies for **all deliveries after the 1st of March 2024** and the switch blocks and actuators CAN NO longer be ordered alone.

New codes are offered with combined operators and switch blocks. The operator and switch blocks are NOT assembled and are packaged separately, as shown below.

Operator picture	OLD References	NEW references	New MOQ and Multiple (standard packaging)
	A01ES-DM	A01ES-DM+A0150B-D A01ES-DM+A0154B-D A01ES-DM+A0150B-DX2307 *** A01ES-DM+A0154B-DX2307 ***	100 (except with X2307 : MOQ 50, multiple 50)
	A01ES-DMX414 *	A01ES-DMX414+A0150B-D * A01ES-DMX414+A0154B-D *	100
	A01ES-DMX413-08 **	A01ES-DMX413-08+A0150B-D ** A01ES-DMX413-08+A0154B-D **	100
	A01ES-DMX1345 A01ES-DMX413-08 A01ES-DMX416 A01ES-DMX417	End of life, last time buy until end of March 2024.	
	A01ES-D	A01ES-D+A0150B-D A01ES-D+A0154B-D	100
	A01ES-DX414 *	A01ES-DX414+A0150B-D * A01ES-DX414+A0150B-DX2307 *,*** A01ES-DX414+A0154B-D *	100 (except with X2307 : MOQ 50, multiple 50)
	A01ES-DF1	A01ES-DF1+A0150B-D A01ES-DF1+A0154B-D A01ES-DF1+A0154B-DX2307 ***	100 (except with X2307 : MOQ 50, multiple 50)
	A01ES-DF2	A01ES-DF2+A0150B-D A01ES-DF2+A0154B-D	100 (except with X2307 : MOQ 50, multiple 50)
	A01ES-DF2-A0150B-D	A01ES-DF2+A0150B-DX2307 ***	
	A01ES-DSP3	A01ES-DSP3+A0150B-D A01ES-DSP3+A0154B-D A01ES-DSP3+A0154B-DX2307 ***	50
	A01ES-DSP3X1345	End of life, last time buy until end of December 2023.	
	A0150B-D A0154B-D	To be associated with an E-stop actuator, see above lines. These codes are stopped.	




\* X414: nut is not mounted, in bags of 100pcs.

\*\*X413-08 : specific marking on the mushroom : red arrows + white ISO marking (Ⓢ)

\*\*\*X2307 : specific packaging, see description hereafter

**2/ A01ES operators and switch block packaging**

Picture of the standard packaging:

<p>Box of 50 contact blocks. Double pole contacts are printed blue. Single pole contacts are printed white.</p>	<p>Box of 20 actuators (except A01ES-DSP3: 10 actuators per box)</p>
	<p>Box of 20 actuators:      A01ES-DSP3 (10pcs) :</p> 
<p>There are 2 boxes of contacts per multiple. (except A01ES-DSP3: 1 box)</p>	<p>Then 5 boxes of actuators are assembled in trays:</p> 



Specific packaging (**X2307 option**), a price adder may apply (please contact your sales representative): the actuator and the contact blocks are delivered in bags. MOQ: 50pcs, multiple: 50pcs.

<p>Example: A01ES-DM+A0150B-DX2307</p>	<p>A01ES-DX414+A0150B-DX2307</p>
	

**3/ A01ES operators and switch block new marking**

Application all deliveries starting from the 1<sup>st</sup> December 2023, depending on the stock situation.

New product marking: New marking for both

Single pole contact blocks are printed white.	Double pole contact blocks are printed blue.
	

On the other side of both contact blocks, CE and UKCA markings and the date code (laser engraving):



**4/ Self Adhesive labels: versions with text are now discontinued**

Self-Adhesive labels: As per the latest ISO 13850, legends are no longer allowed, only a yellow background. The labels with texts are thus end of life, with a last time buy within the stock limit:

Discontinued references	Stock available for last time buy*	Replaced by:
A01YL1	223 pcs	A01YL2
A01YL3	25 pcs	A01YL2
A01YL4	0 – no last time buy possibility	A01YL2

*\* This is the stock situation the day this document was issued and is given for information only. APEM undertakes to honour orders only within the limit of available product stock.*

Vivien Rineau – Product Marketing Manager



Dear All,

After the modification of the red arrows, we qualified our products again according to the EN 60947-5-5.

The main modifications are :

- We cannot deliver the actuator and the switch block separately; they must be delivered together. Thus, there are new codes
- We have adjusted the MOQ and multiple based on the regular packages.
- We take this opportunity to change the marking : we add UKCA.

Following parts has sold to TTI in the last 3 years:

ITEM ID	customer reference
A0150B-D	APEA0150B-D
A01ES-DM+A0154B-D	APEA01ES-DM+A0154B-D
A0154B-D	APEA0154B-D
A01ES-D	APEA01ES-D
A01ES-DF2X413-01	APEA01ES-DF2X413-01
A01ES-DM	APEA01ES-DM
A01ES-DM+A0154B-D	APEA01ES-DM+A0154B-D
A01ES-DMX413-01	APEA01ES-DMX413-01

Those changes will be **effective for all deliveries after March 1<sup>st</sup> 2024.**

Let me know if you have any questions.

Best regards,  
Florian