




PRODUCT UPDATE MEMO

BOURNS® PRODUCTS



Bourns Adjusts Minimum Order Quantity (MOQ) and Multiple Order Quantity (Mult) for Select Products

Riverside, California – May 9, 2023 – Effective immediately for new orders, the Minimum Order Quantity (MOQ) and Multiple Order Quantity (Mult) have changed for select Bourns® products. There is no impact on the form, fit, function, quality or reliability of the component products themselves. A full list of the new changes in MOQ and Mult is included in the following table.

Affected Part Number	Product Line	Old MOQ	New MOQ	Old Mult	New Mult
3006P-1-253	Trimpot	300	2000	100	No Change
3006P-1-253LF	Trimpot	300	2000	100	No Change
3006P-1-253ZLF	Trimpot	300	2000	100	No Change
3006P-1-254	Trimpot	300	2000	100	No Change
3006P-1-254LF	Trimpot	300	2000	100	No Change
3006W-1-253LF	Trimpot	300	2000	100	No Change
3006W-1-254LF	Trimpot	300	2000	100	No Change
3059P-1-253LF	Trimpot	40	2000	20	No Change
3059P-1-253MLF	Trimpot	40	2000	20	No Change
3059P-1-254LF	Trimpot	40	2000	20	No Change
3059Y-1-253	Trimpot	40	2000	20	No Change
3059Y-1-253LF	Trimpot	40	2000	20	No Change
3059Y-1-253MLF	Trimpot	40	2000	20	No Change
3059Y-1-254	Trimpot	40	2000	20	No Change
3059Y-1-254LF	Trimpot	40	2000	20	No Change
3386F-1-253	Trimpot	200	2000	100	No Change
3386F-1-253LF	Trimpot	200	2000	100	No Change
3386F-1-253T	Trimpot	200	2000	100	No Change
3386F-1-253TLF	Trimpot	200	2000	100	No Change
3386F-1-254	Trimpot	200	2000	100	No Change
3386F-1-254LF	Trimpot	200	2000	100	No Change

K2335



Affected Part Number	Product Line	Old MOQ	New MOQ	Old Mult	New Mult
3386F-1-254T	Trimpot	200	2000	100	No Change
3386F-1-254TLF	Trimpot	200	2000	100	No Change
3386G-1-253	Trimpot	200	2000	100	No Change
3386G-1-253LF	Trimpot	200	2000	100	No Change
3386G-1-254	Trimpot	200	2000	100	No Change
3386G-1-254LF	Trimpot	200	2000	100	No Change
3386P-1-253	Trimpot	200	2000	100	No Change
3386P-1-253LF	Trimpot	200	2000	100	No Change
3386P-1-253T	Trimpot	200	2000	100	No Change
3386P-1-253TLF	Trimpot	200	2000	100	No Change
3386P-1-254	Trimpot	200	2000	100	No Change
3386P-1-254LF	Trimpot	200	2000	100	No Change
3386P-1-254T	Trimpot	200	2000	100	No Change
3386P-1-254TLF	Trimpot	200	2000	100	No Change
CR0402-FX-1470GLF	Fixed Resistors	10000	20000	1000	10000
MF-USMF175X-2	Multifuse	3000	9000	3000	No Change
PTVS20-015C-H	TSP	500	1000	200	1000
PTL30-10R1-502B2	Sensors & Controls	1200	No change	600	1200

If you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).